

SAMPLE AUTO DIAGNOSTICS LTD

Vehicle Diagnostic Report

Tel: 01234 567890
Email: info@exampleautodiagnostics.example
Address: 1 Example Way, Sampleton, SA1 2BC

Report ID: RPT-000001
Test Time: 2026-06-30 07:33
Technician: J. Smith

Vehicle Information

Field	Value	Field	Value
Vehicle	2018 (J) Volkswagen CV	VIN	WVWZZZ1KZJW000001
Mileage	45,213 miles	Registration	FAKE 123
Customer	Joe Bloggs	Telephone	07000 000000
Scanner	AutoScan Pro MS900	Version	V13.60

System Scan Results

System	Status	DTC Count
01 - Engine Control Module 1	FAULT	1
03 - Brakes 1	OK	0
04 - Steering Angle Sender	OK	0
08 - Air Conditioning	OK	0
09 - Electronic Central Electric	OK	0
13 - Adaptive Cruise Control	OK	0
15 - Airbag	OK	0
17 - Instrument Cluster	OK	0
19 - Gateway	OK	0
25 - Immobilizer	OK	0
5F - Infotainment Electronics	OK	0
61 - Battery Regulation	OK	0

Diagnostic Trouble Codes

DTC	Description	Status
P040100	Exhaust Gas Recirculation Flow, Insufficient Detected	Passive / Sporadic

Technician Notes

Sign-off

Customer: _____ Date: _____